DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/12/2016 FORM APPROVED OMB NO. 0938-0391

MANIE OF PROVIDER OR SUPPLIES CARDINAL SERVICES INC OF INDIAN STREET ADDRESS, CITY, STATE, ZIP CODE 330 E COLUMBIA LOGANSPORT, IN 45947	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED	
APOST SURVEY REVISES (PSR) to the Life Safety Code Recertification Survey conducted on 02/02/16 was conducted by the Indiana State Department of Health in accordance with 42 CFR Subpart 483.470(j). Survey Date: 100/245450 At this PSR survey, Cardinal Services Inc. of Indiana was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j). Life Safety Code (LSC), Chapter 33, Existing Residential Board and Gare Occupancies. This one story facility was sprinktered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and hard wired smoke detectors in resident rooms. The facility has a capacity of eight and had a census of eight at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA	15G549		15G549	B. WING			R 04/04/2016	
PREFIX TAG REGULATORY OR ISC IDENTIFYING INFORMATION PREFIX TAG CROSS REFERENCED TO THE APPROPRIATE CROSS REFERENCEDED CROSS REFERENCED CROSS REFERENCED CROSS REFERENCED CROSS REFERENCED CROSS REFERENCED CROSS REFERENCED CROSS REFE					330 E COLUMBIA			
A Post Survey Revisit (PSR) to the Life Safety Code Recertification Survey conducted on 02/02/16 was conducted by the Indiana State Department of Health in accordance with 42 CFR Subpart 483.470(i). Survey Date: 04/04/16 Facility Number: 001063 Provider Number: 150549 AIM Number: 100245450 At this PSR survey, Cardinal Services Inc. of Indiana was found in compiliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(i), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was sprinklered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and hard wired smoke detectors in resident rooms. The facility has a capacity of eight and had a census of eight at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA	PRÉFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFI	(EACH	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETION
Department of Health in accordance with 42 CFR Subpart 483.470(j). Survey Date: 04/04/16 Facility Number: 001063 Provider Number: 150549 AIM Number: 100245450 At this PSR survey, Cardinal Services Inc. of Indiana was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j). Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was sprinklered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and hard wired smoke detectors in resident rooms. The facility has a capacity of eight and had a census of eight at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA	{K 000}	A Post Survey Revisi	it (PSR) to the Life Safety	{K 0	00}			
Facility Number: 001063 Provider Number: 150549 AIM Number: 100245450 At this PSR survey, Cardinal Services Inc. of Indiana was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470[jl. Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was sprinklered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and hard wired smoke detectors in resident rooms. The facility has a capacity of eight and had a census of eight at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA		Department of Health in accordance with 42 CFR Subpart 483.470(j).						
Indiana was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was sprinklered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and hard wired smoke detectors in resident rooms. The facility has a capacity of eight and had a census of eight at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA		Facility Number: 001 Provider Number: 15	063 G549					
facility has a fire alarm system with smoke detection in the corridors, common living areas and hard wired smoke detectors in resident rooms. The facility has a capacity of eight and had a census of eight at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA		Indiana was found in Requirements for Par CFR Subpart 483.470 and the 2000 edition Protection Association Code (LSC), Chapter	compliance with ticipation in Medicaid, 42 D(j), Life Safety from Fire of the National Fire n (NFPA) 101, Life Safety 33, Existing Residential					
(E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.73. Quality Review completed on 04/11/16 - DA		facility has a fire alarr detection in the corrid and hard wired smoke rooms. The facility ha	n system with smoke lors, common living areas e detectors in resident as a capacity of eight and					
		(E-Score) using NFPA Approaches to Life Sa	A 101A, Alternative afety, Chapter 6, rated the					
	LABORATORY					TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.